



WORKPLACE INSTRUCTION 9/2010

BOLLARDS OUT OF SERVICE

Version	Date	Reason for Change	Document/ Para Ref	Made By	Description of Change
1.0	14 May 2010	Initial Version		Terry O'Connor	Initial Version – approved by Terry O'Connor (GMLO)

Prelude:

The following is a summary of mandatory controls and corrective actions applicable to the identified risk. All stated corrective actions or safety directions stated below must be complied with to ensure that all known risks are controlled.

The summary has been prepared in accordance with the requirements of Regulation 39 of the WORKPLACE HEALTH AND SAFETY REGULATIONS *as in force at 1 July 2008*

Introduction:

Bollards are required to be taken out of service when repair work is being effected on tie rods in the adjacent area.

Instruction:

Bollard Number 8 has been returned to service

Bollard Number 9 has been tagged out of service and is not to be used until further notice.

**ISSUED TO: Patricks Stevedores
P&O Stevedores
NT Shipping
DPC Cargo
DPC Maintenance**

DARWIN PORT CORPORATION	Issue Status	Issue 1
	Issue Date	Friday 14 May 2010
	Authorisation	Terry O'Connor
	Signed	