



WORKPLACE INSTRUCTION 5/2010

SAFETY GUARDS ON BULK ORE HANDLING EQUIPMENT AT EAW

Version	Date	Reason for Change	Document/ Para Ref	Made By	Description of Change
1.0	6 May 2010	Initial Version		Terry O'Connor	Initial Version – approved by Terry O'Connor (GMLO)

Prelude:

The following is a summary of mandatory controls and corrective actions applicable to the identified risk. All stated corrective actions or safety directions stated below must be complied with to ensure that all known risks are controlled.

The summary has been prepared in accordance with the requirements of Regulation 39 of the WORKPLACE HEALTH AND SAFETY REGULATIONS *as in force at 1 July 2008*

Introduction:

A practice of removing guards to work in the area protected has highlighted issues in regards non replacement of safety guards on equipment being operated at EAW.

Instruction:

Running equipment requires safety guards in a number of positions. These guards often have to be removed to effect repairs or cleaning. If removing any safety guards, the equipment must be tagged out. Before the tags are replaced, all safety guards to be replaced.

Walk thru inspections prior to equipment starting are mandatory to ensure all safety guards are in place.

ISSUED TO: Territory Resources
OM Manganese
Patricks Stevedores
P&O Stevedores
Viola Environmental Cleaning
Freightlink DPC Cargo DPC Engineering

DARWIN PORT CORPORATION	Issue Status	Issue 1
	Issue Date	Thursday 6 May 2010
	Authorisation	Terry O'Connor
	Signed	<i>Tee</i>
	Date	<i>14/5/10</i>