

WORKPLACE INSTRUCTION 7/2010

USE OF FHW MOORING DOLPHIN

Version	Date	Reason for Change	Document/ Para Ref	Made By	Description of Change
1.0	6 May 2010	Initial Version		Terry O'Connor	Initial Version – approved by Terry O'Connor (GMLO)

Prelude:

The following is a summary of mandatory controls and corrective actions applicable to the identified risk. All stated corrective actions or safety directions stated below must be complied with to ensure that all known risks are controlled.

The summary has been prepared in accordance with the requirements of Regulation 39 of the WORKPLACE HEALTH AND SAFETY REGULATIONS *as in force at 1 July 2008*

Introduction:

Due to no lighting, the use of the mooring Dolphin at FHW at night has been identified as presenting an unnecessary danger

Instruction:

Until proper lighting is installed, the Dolphin at FHW is not to be used at night. This applies to all vessels including Defence.

ISSUED TO: Patricks Stevedores
P&O Stevedores
DPC Cargo
DPC Pilots
DPC Shipping Supervisor
Naval Port Services Manager

DARWIN PORT CORPORATION	Issue Status	Issue 1
	Issue Date	Thursday 6 May 2010
	Authorisation	Terry O'Connor
	Signed	<i>Tee</i>
	Date	<i>14 May 10</i>